

Revision Date 07-Aug-2017

Revision Number 4

**1. IDENTIFICATION**

**Product Identifier**

**Product Name** GIA1042

**Other means of identification**

**Product Code(s)** GIA1042

**Product Type** Hot Melt Adhesive

**Recommended use of the chemical and restrictions on use**

**Recommended Use** Adhesives

**Uses advised against** No information available

**Details of the supplier of the safety data sheet**

**Supplier Address**

Glue Machinery Corporation  
4234 Boston Street  
Baltimore, MD 21224

**Emergency telephone number**

**Company Phone Number** 888-202-2468

**Emergency Contact Number** Chem-Tel 1-888-255-3924

**2. HAZARD IDENTIFICATION**

**Classification**

Remove contact lenses, if present and easy to do. Continue rinsing  
IF ON SKIN: Gently wash with plenty of soap and water  
If skin irritation or rash occurs: Get medical advice/attention

**Precautionary Statements - Storage**

Store in accordance with local regulations  
Store in a dry place

**Precautionary Statements - Disposal**

Dispose of in accordance with federal, state and local regulations

**Hazards not otherwise classified (HNOC)**

Contact with product at elevated temperatures can result in thermal burns  
Avoid breathing vapors or fumes from hot material

**Other Information**

Unknown acute toxicity 0 % of the mixture consists of ingredient(s) of unknown toxicity

**3. COMPOSITION/INFORMATION ON INGREDIENTS**

**Substance**

**Synonyms** Hot Melt Adhesive.

Components	CAS No.	Weight-%	Trade Secret
Paraffin	Proprietary	1-5%	*

\*The exact percentage (concentration) of composition has been withheld as a trade secret.

**4. FIRST AID MEASURES**

**Description of first aid measures**

**Eye Contact** Rinse immediately with plenty of water, also under the eyelids, for at least 15 minutes.  
Contact with molten material: Cool with cold water immediately. Do not remove adhesive.

**Skin Contact** Wash skin with soap and water. Contact with molten material may cause severe burns.  
Immediately cool affected skin as long as possible with cold water. Do not remove clothing if adhering to skin. Removal of solidified molten material from skin requires medical assistance. Seek immediate medical attention/advice.

**Inhalation** Remove to fresh air.

**Ingestion** None under normal use conditions. Clean mouth with water and drink afterwards plenty of water. Do NOT induce vomiting. Never give anything by mouth to an unconscious person. Consult a physician if necessary.

**Notes to Physician** Treat symptomatically.

**5. FIRE-FIGHTING MEASURES**

**Suitable Extinguishing Media**

Use, Foam, Dry chemical or CO2

Unsuitabl8

## 6. ACCIDENTAL RELEASE MEASURES

### Personal precautions, protective equipment and emergency procedures

#### **Personal Precautions**

Ensure adequate ventilation. Use personal protection equ



**Appearance**  
**Color**

Yellow Glue sticks chips or



Components	Oral LD50	Dermal LD50	Inhalation LC50
------------	-----------	-------------	-----------------

[Empty row for data entry]

[Empty row for data entry]

[Empty row for data entry]

[Empty row for data entry]

TSCA - United States Toxic Substances Control Act Section 8(b) Inventory  
DSL/NDSL - Canadian Domestic Substances List/Non-Domestic Substances List

**US Federal Regulations**

**SARA 313**

Section 313 of Title III of the Superfund Amendments and Reauthorization Act of

